


CORNER RECORD

Document Number CR 9017

City of OAKLAND County of ALAMEDA, California

Brief Legal Description INTERNATIONAL BOULEVARD AND 107TH AVENUE



CORNER TYPE

Government Corner ☐ Control ☒
 Meander ☐ Property ☐
 Rancho ☐ Other ☐
 Date of Survey 07/21/2016

COORDINATES (Optional)

N. _____
 E. _____
 Zone _____ NAD27 ☐ NAD83 ☐
 NAD83 Epoch _____
 Elev. _____
 Vet. Datum: NGVD29 ☐ NAVD88 ☐
 Meas. Units: Metric ☐ Imperial ☒

Corner — Left as found ☒ Found and tagged ☐ Established ☐ Reestablished ☐ Rebuilt ☐

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:
FOUND 1/8" IRON PIN IN CONCRETE, LOCATED IN CENTER OF 107TH AVENUE AT THE INTERSECTION OF
INTERNATIONAL BOULEVARD AND 107TH AVENUE.

A description of the physical condition of the monument as found and as set or reset: _____
SET NAIL AND TAG, STAMPED LS 8593 AS REFERENCE POINTS TO BE USED TO RESET MONUMENT SHOULD IT
BE DISTURBED DURING CONSTRUCTION ACTIVITIES.
SEE SHEET 2 FOR GRAPHIC


SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with
 the Land Surveyor's Act on AUGUST 17, 20 16
 Signed [Signature] P.L.S. or R.C.E. No. _____ L.S. # 8593



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received 6 OCTOBER 20 16
 and examined and filed 27 OCTOBER 20 16
 Signed Michael Rubner P.L.S. or R.C.E. No. 6843
 Title COUNTY SURVEYOR



County Surveyor's Comment: _____

